

✓
CORNER RECORD

COUNTY OF MADERA T. 8 S. R. 23 E M.D.B. & M. MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 20 19 77



NORTH 1/4 CORNER SECTION 6 8/23

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

SET BY SINGLE PROPORTIONATE DISTANCE BETWEEN
NW CORNER SECTION 6 8/23 AND NW COR. SECTION 4 8/23.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 1" x 30" IRON PIPE - UP 10" IN STONE MOUND

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

250' ± WEST OF FOREST SERVICE ROAD
11" YELLOW PINE S. 5° 32' W. 19.30' } I BLAZED
20" BLACK OAK N. 21° 07' E. 81.65' }
1.5' WEST OF 3 1/2" STEEL POST

J.N. 77-104

F.B. 550/16

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON DECEMBER 15 19 78

SIGNED: William D. Gentry
L.S. or B.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____
AND EXAMINED AND FILED _____ 19 _____

BY: _____
TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO