


CORNER RECORD

COUNTY OF MADERA T. 9S. R. 17E. M.D.B.# MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 10 1976



WEST 1/4 CORNER SECTION 12

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 3/4" I.P. - R.C.E. 12406 - UP 6" ± (BENT)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

REPLACED WITH 3/4" x 15" IRON PIPE - L.S. 2737 - 5" DOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

20.00' WEST OF 3/4" I.P. - L.S. 2737 - 4" DOWN.
12.54' NW OF ○ E/S TEL. POLE
17.3' E. OF PL N. (OMIT 2ND POLE)
79.54' NE ✓ ○ IN E/S TRANS. & LIGHT POLE.
40' ± W ✓ TEL LINE S. (OMIT 1ST POLE.)
J.N. 76-145 F.B. 545 p. 49

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 22 1976.

SIGNED: William D. Gentry

L.S. or R.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 12-6 1976 AND EXAMINED AND FILED 12-10 1976.

BY: A. Grate

TITLE: County Engineer

DOCUMENT No. 36-37-01

STATEMENT ON BACK OF SHEET

YES

NO