CORNER R	ECORD
COUNTY OF MADERA T. 9 S. R. 17	E. M.D.B. & MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CORNER IDENTIFICATION — DATE OF VISIT	CONTROL OTHER
NW COR. SEC. 31, T	.45., R.IIE.
CORNER — LEFT AS FOUND X FOUND AND TAGGED REESTAL	BLISHED OBLITERATED CORNER REBUILT
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH	
FOUND 3/4" IRON PIPE, DOWN	12"
TAGGED RCE 18489	
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND	THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY COUNTY NORTHINGS (Y)	OTHER STATION STATION
(Fold	n de la companya de Na companya de la co
	9
SKETCH: (Include reference tie or witness points, remarks and topo of	area)
The state of the s	
SHINER IN	SHINER IN P.P.
UTILITY POLE	38.10
37.901	
No SCALE	Fd. 3/4" I.P. 12" DN.
SHINER IN WELL	
	. /2·
	SHINER IN P.P.
SURVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	THE CORNER REGORD WAS RECEIVED
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT	AND EXAMINED AND FILED
4 2 2	TITLE:
L.S. or R.C.E. No.: RCE 3050 VO D. NO.	DOCUMENT No.
15/38. · · · · · · · · · · · · · · · · · · ·	STATEMENT ON BACK OF SHEET
(日本) (新年) (新年) (新年) (新年) (新年) (新年) (新年) (新年	YES NO
Exp. 3/31/88	