

CORNER RECORD

COUNTY OF MADERA T. 9 S. R. 17 E. MD MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT FEB. 15 1992



NORTHWEST CORNER SECTION 35

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT


PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

I FOUND A 3/4" IRON PIPE, TAGGED LS2737 (GENTRY) ONE FOOT WEST OF A RAILROAD TIE FENCE POST FOR THE CORNER OF SECTIONS 26, 27, 34, AND 35. THE RAILROAD TIE FENCE POST IS AN ANGLE POINT IN A NORTH/SOUTH FENCE LINE. THERE ARE NO OTHER SUITABLE TIES.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEB. 15 1992
 SIGNED: [Signature]
 L. or R.C.E. No. LS 4126

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED 2-28 1992
 AND EXAMINED AND FILED 3-30 1992
 BY: Dove Stinson
 TITLE: Madera County Eng'r.
 DOCUMENT No. _____

SEAL

STATEMENT ON BACK OF SHEET YES NO