


CORNER RECORD

COUNTY OF MADERA T. 9S R. 19E M.D.B. & MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT JUNE 23 19 78



NORTH 1/4 CORNER SECTION 6

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 RESET ALONG TRUE LATITUDE CURVE ON SECOND STANDARD PARALLEL SOUTH ON PRORATION OF GOV'T RESURVEY OF 1965 USING SW CORNER SEC. 36 8/18 AND NE COR SEC. 5 9/19

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
 SET 1 1/2" x 30" IRON PIPE - L.S. 2737 - UP 8"

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)
 60.60' SE OF SW CORNER CEMETERY FENCE.
 50.40' S. OF FENCE NE/SW.
 43.00' E. OF FENCE NORTH.
 FROM WHICH BEARS:
 2" IRON PIPE (I TAGGED L.S. 2737) S 28° 50' 24" W. 91.46' SW COR. RAYMOND CEMETERY SITE
 24" WHITE OAK S. 22° 41' 10" W. 114.47' SMALL NOTCH N/S
 24" WHITE OAK S. 89° 31' 25" W. 88.04' SMALL NOTCH SE/S

J.N. 78-090

F.B. 556/8

SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON JUNE 27 19 78.
 SIGNED: William D. Gentry
 L.S. & C.E. No.: 2737

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED Sept 15 19 78.
 BY: A. Brata
 TITLE: County Engineer
 DOCUMENT No. _____
 STATEMENT ON BACK OF SHEET YES NO

SEAL