


CORNER RECORD

COUNTY OF MADERA T. 8 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT MAY 1989



W 1/4 SECTION 2 8/19

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
METHODS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference)

W 1/4 CORNER SECTION 2 8/19

FOUND 1" IRON PIPE UP 6, TAGGED L.S. 2737 IN A 2 1/2' DIA. X 1/2' HIGH ROCK MOUND.

ORIGINAL BEARING TREE:

1. A 13.4' DIA. WHITE OAK WITH SCRIBING BEARS S. 67 1/4° W. 27.7 (S67° W. 27.7')

FOUND 3/4" IRON PIPE, FLUSH, TAGGED L.S. 2737 AT FENCE CORNER 147' W'LY OF CORNER - NOT ACCEPTED FENCES RUN N'LY AND E'LY FROM THE FENCE CORNER

TIES ON FILE SEE CORNER RECORD BY W.O. GENTRY DATED MARCH 10, 1989.

COPIED FROM R.S. BY SEIB-LS. 5509 36/45-46

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET