


CORNER RECORD

COUNTY OF MADERA T. 9S. R. 18E. M.D.B. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT NOVEMBER 9 19 76



WEST 1/4 CORNER SECTION 6

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 2" I.P. - RCE 10581 - UP 13"

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

RESET PIPE TO 3" UP & RESET TAG RCE 10581

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

1.0 SW OF FENCE POST
ON LINE ROW FENCE POSTS' NORTH

4.5' SE OF FENCE. NE/SW

72" OAK S. 55° 43' 45" E. 80.80'

54" DEAD OAK (DOWN) S. 39° 51' E W. 66.50' ±

33" OAK N. 61° 09' 30" W. 53.21' (I BLAZED)

J.N. 76-145

F.B. 545/50, 52

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON NOVEMBER 19, 19 76.

SIGNED: William D. Gentry

L.S. OR R.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED DECEMBER 6 19 76 AND EXAMINED AND FILED Dec 13 19 76.

BY: A. Rosta

TITLE: County Engineer

DOCUMENT No. 76-37-06

STATEMENT ON BACK OF SHEET

YES

NO