

CORNER RECORD

COUNTY OF MADERA T. 5 R. 21 MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT 20 SEPT. 1979

35

EAST QUARTER CORNER SEC. 35

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
 FOUND 2" CAPPED IRON PIPE USFS 1943.
 IDENTIFIED BY GOV'T. NOTES, F.S. NOTES, F.S. TIES + PLACARDS.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
 SEE ABOVE


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

CORNER IS LOCATED ON WESTERLY SLOPE OF HILL APPROX 1000 FEET EAST OF CAMP SUGAR PINE ROAD



NOTE: ALL AZIMUTHS ARE MAGNETIC.



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON OCT 2 1979.
 SIGNED: Jack W. Kunz
 L.S. or C.E.D. No.: 12278

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED Dec 18, 1979.
 BY: A. Krote
 TITLE: County Engineer
 DOCUMENT No. _____