


CORNER RECORD

COUNTY OF MADERA T. 5 S R. 21 E M D B & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT _____ 19____



W 1/4 COR. SEC. 35

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

RS 1987-41
REC. VOL — PG. — OF CMARS M.C.O.R.
1987

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

4

FOUND 1 1/2" I.P. WITH 2" BRASS CAP IN 24" DIA. ROCK MOUND 12" ABOVE GROUND.
POST & SIGN N45°E, 3° FT.

FOUND BT'S:
30" PINE S69°45'E,
38" FT. HEALED FACE,
14" CEDAR, N83°34'W,
25" FT. HEALED FACE

NEW BT'S:
8" CEDAR, N59°E,
21" FT. SCRIBED
"1/4 535 BT"

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO