


CORNER RECORD

CITY OF MADERA T. 5 R. 21 MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT MAY 1990



N 1/4 SEC. 36 5/21

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

CAP INSCRIPTION DESCRIPTION

TSS R 21 E.
 S 25.
 1/4 S 36
 LS 5509
 1989

N 1/4 CORNER SECTION 36 5/21
 FOUND A 2' DIA. ROCK MOUND, FLUSH. REMONUMENTED WITH
 FSM. UP 6". REBUILT ROCK MOUND 2' DIA. X 1/2' HIGH AROUND
 MONUMENT.
 ORIGINAL BEARING TREES:
 1. A DETERIORATED PINE STUMP BEARS N.14° E 27.7'. (N 16° 20' E 25.74')
 2. A BLACK-OAK, 19" DIA., BEARS S 17 1/2° E 19.0'. (S 16° 30' E, 18.48')
 NEW TIES:
 3. A N INCENSE CEDAR, 8" DIA., BEARS N 88 3/4° W 47.12'.
 4. A BLACK OAK, 17" DIA., BEARS N 41 1/2° E, 63.10'.
 5. A WHITE FIR, 15" DIA., BEARS S 51 1/4° E, 11.56'.
 - SET METAL POST WITH FOREST SERVICE MONUMENT SIGNS
 ATTACHED 4' E NW OF THE CORNER.

PHYSICAL DESC

IFORNIA C
 IATIONS USE
 ZONE

NOXIMINGS (T)

EASTINGS (X)

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 37/61,62

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO