


CORNER RECORD

Document Number 591221 B

City of _____ County of Madera, California

Brief Legal Description Portion of Section 12, T.5S., R.22E., M.D.B. & M.



CORNER TYPE

COORDINATES
(Optional)

Government Corner Control
Meander Property
Rancho Other
Date of Survey Oct. 23, 1995

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Corner No. 1 of the Cornucopia per Mineral Survey 5049AB. Found 3' diameter rock mound, also found original bearing trees.

A description of the physical condition of the monument as found and as set or reset: Set 5/8" diameter bar with plastic cap LS 5339 at center of rock mound.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 12/21 1995.

Signed [Signature] L.S. or R.C.E. Number 5339




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 22 DEC 1995 and examined

and filed 29 JAN 1996.

Signed [Signature] Title Act. Co. Surveyor



County Surveyor's Comment _____



No Scale.

