


USDA-FOREST SERVICE
Index
File No. _____

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or
Survey No. _____ Cor.
No. _____

R. _____ R.D. _____ County _____
Merid. _____ N.F. _____ State _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found 3/4" I.P. in rock mound. 2

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found a 24" tamarack (South 52° West, 10.56') and cut open to expose scribing. Accepted heal in 29" tamarack (North 51° West, 15.18') without cutting open. 3

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature 7

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Go north on Beasore Road approximately 1 mile past Road 6S01. Turn northwesterly on logging road. At approximately 1 mile the road turns southwesterly. Proceed 300' to creek flowing southerly. Follow creek into meadow and walk along east side to corner. 4

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency 8

Signature _____ Title _____ Division _____ Headquarters _____ Date _____ FS-7100-52 (3/68) 5

CORNER RECORD (PERPETUATION)

MONUMENT. DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Reset with a U.S.F.S. monument in a rock mound. Marked corner to Section 28, Section 29, Section 32 and Section 33, Township 5 South, Range 23 East. 9

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I blazed a 24" tamarack North 11° East, 70.30' and a 9" fir North 64° East, 17.49'. I set a U.S.F.S. post South 45° East, 2.0'. Edge of meadow is west 27.00'. 10

Work Done By Jones Title Surveyor Date _____ State Registration No. or Agency LS 4298 11

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Index File N T. R. M. Tract or S. No. Cor. 12