

CORNER RECORD

COUNTY OF MADERA TOWNSHIP 5 SOUTH, RANGE 23 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [x] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: September 19 73

33

WEST 1/4 CORNER OF SECTION 33, 5/23.

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT [x]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found rock mound and Gov't. tags.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 3/4" Iron Pipe tagged "RCE 12406".

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION STATION

ZONE ELEVATION NORTHINGS (Y) EASTINGS (X)

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

Note: Copied from Parcel Map 664
Surveyed by R.W. Greenwood, RCE 12406

VOL 19 PAGE 142

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

19

SIGNED:

L.S. or R.C.E. No:

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 19

AND EXAMINED AND FILED 19

BY:

TITLE:


DOCUMENT No: STATEMENT ON BACK OF SHEET: YES [] NO []

File No. _____
T. _____ R. _____
Merid. _____

CORNER RECORD (SEARCH)
(Ref. FSM 7151.4)

Tract or Survey No. _____
Cor. W 1/4 33
No. _____
R.D. _____ County _____
N.F. _____ State _____

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found 3/4" I.P. in small rock mound.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found 20" tamarack and cut into to expose scribing. Took wood sample for ring count. Blaze faces South 60° East, but corner lies South 70° East, 10.35 feet.

PHOTO IDENTIFICATION DATA

Photo No. _____
Filed At. _____
Object Ident. _____
Ident. By _____
Signature _____

PLANE COORDINATE POSITION DATA

State _____ Zone _____
X _____
Y _____
Estab. By _____
Agency _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Go north on Beasore Road approximately 1/2 mile past Road 6S01. Turn easterly on old logging road with large log across entrance. Proceed for 500' and turn north towards meadow. Corner is on southwest edge of meadow.

Signature _____ Title _____ Division _____ Headquarters _____ Date _____
FS-7100-52 (3/68)

0523

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Reset with U.S.F.S. monument in rock mound marked 1/4 corner Section 32 and Section 33, Township 5 South, Range 23 East.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

I blazed a 21" tamarack South 66° East, 40.26' and a 20" tamarack South 88° West, 31.48'. I set a U.S.F.S. post North 45° East, 4.0'.

Work Done By. Jones Title Surveyor Date _____ State Registration No. or Agency LS 4298
Certified Cor. Record Prepared? Yes No Filed At _____ Date _____

REMARKS

Index File No. T. R. M. Tract or Surv. No. Cor. _____