

CORNER RECORD

COUNTY OF MADERA TOWNSHIP 5 SOUTH, RANGE 23 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: September 19 73



NORTHWEST CORNER OF SECTION 34, 5/23.

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT [X]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found rock mound.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 3/4" Iron Pipe tagged "RCE 12406".

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION STATION

ZONE ELEVATION NORTHINGS (Y) EASTINGS (X)

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

Note: Copied from Parcel Map 664
Surveyed by R.W. Greenwood, RCE 12406

VOL 19 PAGE 142

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

19

SIGNED:

L.S. or R.C.E. No:

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 19

AND EXAMINED AND FILED 19

BY:

TITLE:

DOCUMENT No: STATEMENT ON BACK OF SHEET: YES [] NO []

Faint, illegible text at the top of the page, possibly a header or title.

Faint, illegible text in the middle section of the page.

Faint, illegible text in the middle section of the page.

Faint, illegible text at the bottom of the page, possibly a footer or reference.

0523400200

CORNER RECORD

COUNTY OF Madera T. 5 S. R. 23 E. M.D.B. & M. MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT August 15 85



The northwest corner of section 34 5/23.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
Found and Accepted: A 1" O.D.I.P., 30" long, up 12", tagged LS 4727 in a 3' dia. x 1/2' high rock mound. Found 2 original bearing trees per GLO field notes of J. M. Anderson U.S. Deputy Surveyor 1881.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
 Remonumented found pipe with F.S.M., up 8". Rebuilt rock mound 4 1/2' x 3' x 1' high around monument. Set a metal post with Forest Service monument signs attached 4' ± NW of the corner. Placed found monument inside of F.S.M..

F.S.M. - Aluminum monument, 2 1/2" O.D., 30" long with a 3 1/4" O.D. aluminum cap stamped for the corner, with LS 4689, the date and the Forest Service logo.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

Corner Ties:

Original Bearing Trees:

1. A Pine stump 60" dia., bears N 46° 59' E, 39.6'.
(No Nail)
2. A Ponderosa Pine, 44" dia. with visible scribing, bears S 81° 00' E, 32.3. (No Nail)

Cap Inscription

T 5 S R 23 E
 S 28 | S 27
 S 33 | S 34
 LS 4689
 1985

New Bearing Objects:

3. A Tamarack, 11.5" dia., bears N 14° 15' E, 41.29'.
4. A chiseled "+" in a rock 3' x 5' x 4 1/2' high, bears N79° 02' 00" E, 38.68'.
5. A Ponderosa Pine, 18.5" dia., bears S 55° 56' E, 50.05'.

V-13
 F.B. 34/73
 Job No. 85-9
 (Continued on back)

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED BY HOWARD ARNOLD COHEN IN DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON October 9 1985

SIGNED: Howard Arnold Cohen
 L.S. No. 4689

LS 4689
 SEAL
 STATE OF CALIFORNIA

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED BY William A. Jensen ON Nov 31 1985

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET YES NO

6. A chiseled "+" in a rock, 2' x 3' x 1 1/2' high, bears S 81° 27' 54" W, 51.34'.

7. A P.K. nail and tag (LS 4689) in a rock, bears N 17° 12' 18" W, 23.32'.

The corner lies on the N'ly side of a large rock outcrop.

Bearings are to the center of trees at the base. Distances are horizontal to a nail and tag (stamped LS 4689) driven into the side center of the root crown, unless otherwise noted.

Posted Forest Service monument and bearing tree signs.

Stamped monument in accordance with the BLM 1973 "Manual of Surveying Instructions".

Fences run north, east, and south from the corner.

0523 400208

