


CORNER RECORD

COUNTY OF MADERA T. 5 S. R. 24 E. M.D.B. & MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT November 19 78



CENTER 1/4 CORNER SECTION 14

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Position established by intersection.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 2" dia. Aluminum pipe, 25" long with 3 1/4" Aluminum cap stamped "L.S. 3670 - 1978" up 6" in 1' dia. rock mound.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

<p>N 26° 15' E , 6.87'</p> <p>S 82° 00' E , 26.06'</p> <p>S 01° 00' E , 32.79'</p> <p>N 80° 15' W , 13.54'</p>	<p>Set nail and washer stamped "L.S. 3670" at base of 6" dia. Lodgepole Pine, on right side.</p> <p>Set nail and washer stamped "L.S. 3670" at base of 4" dia. White Fir, on right side.</p> <p>Set nail and washer stamped "L.S. 3670" at base of 15" dia. Lodgepole Pine, on right side.</p> <p>Set nail and washer stamped "L.S. 3670" at base of 6" dia. Lodgepole Pine, on right side.</p>
--	---

NOTE: Copied from Record of Survey for Southern California Edison Co. by Robert S. Hodson L.S. 3670

SURVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE
<p>THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____</p> <p>SIGNED: _____</p> <p>L.S. or R.C.E. No.: _____</p> <p style="text-align: center;">SEAL</p>	<p>THE CORNER RECORD WAS RECEIVED _____ 19____</p> <p>AND EXAMINED AND FILED _____ 19____</p> <p>BY: _____</p> <p>TITLE: _____</p> <p>DOCUMENT No. _____</p> <p>STATEMENT ON BACK OF SHEET YES <input type="checkbox"/> NO <input type="checkbox"/></p>