CORNER RECORD

	•
COUNTY OF MADERA TOWNSHIP 5 SOUTH, RANG	SE 24 EAST, M.D.B.&M. CALIFORNIA
	RANCHO CONTROL OTHER C
CORNER IDENTIFICATION - DATE OF VISIT: November	
NORTH & CORNER OF SEC	TTON 15. 5/24.
	,1101 10, 0, 11
CORNER - LEFT AS FOUND FOUND AND TAGGED REESTA	BLISHED OBLITERATED CORNER REBUILT
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHO	DD USED TO IDENTIFY OR REESTABLISH
Found nothing - Position established	
per Gov't. notes. Position accepted	
10 & 15. Durable monument can NO PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	
S 89°16'34"W, 25.00 feet - Set Witne Aluminum Pipe, 25" long with 3½" Al.	
up 8".	cap scamped in 3070 - 1370
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST	SECOND THIRD
	COUNTY OTHER STATION STATION
ZONE ELEVATION NORTHI	
SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARK	S AND TOPO OF AREA)
TIES:	
S 51°01'E, 10.56 feet Found ori	ginal bearing tree to be a 24" dia.
· · · · · · · · · · · · · · · · · · ·	Pine with grown over blaze on
NorthWest	side.
	ginal bearing tree to be a dead
	pole Pine with blaze on NorthEast 4 S B T " visible.
S 89°16'34"W, 25.00 feet Set witne	
Note: Copied from Record of Survey f	· · · · · · · · · · · · · · · · · · ·
Surveyed by Robert S. Hodson,	LS 3670.
SURVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	THE CORNER RECORD WAS RECEIVED 19
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON	AND EXAMINED AND FILED
19	BY:
SIGNED:	TITLE:
L.S. or R.C.E. No:	

SEAL

DOCUMENT NO: STATEMENT ON BACK OF SHEET: YES

ио 🔲