

Index File No. _____

CORNER RECORD (SEARCH)

(Ref. FSM 7151.4)

T or Survey No. _____

(32)

Cor. No. Sec 12


T 6N R. 20E

R.D. _____ County Mariposa

Merid. MDAEM.

N.F. Sierra State Ca

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

Found no evidence of original corner.

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Nothing found

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

From the junction of Warner Rd. & Highway 49, the corner is located northerly 725', 2' west of the Highway ~~is~~ easterly right-of-way fence.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature _____
 Title _____
 Division _____
 Headquarters _____
 Date 10/10/89

FS-7100-52 (3/68)

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set std. U.S.F.S. monument, 2 1/2" O.D. aluminum pipe, 30" long, with 3/4" aluminum cap, no rocks available, marked:

T6S
 R20E 1/4 R21E
 S12 T57
 1989 LSS339

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

1. A pine, 9" diameter, blazed end scribed "WBT", bears N08°54'E 24.46'
2. " " , 11" " " " " " " 583°53'E 7.32'
3. " " 25" " " " " " " " N59°42'W 8.51'
4. Set 2 metal post with 54-5 & 54-7 signs 545°W, 4'
5. A 1" dia l.o. with tag LS2737 bears S17°02'17"E 79.22'

Work Done By R. Seaman Title L.S. Date 10/9/89 State Registration No. 5339 or Agency _____

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

Bearings are to the center of the trees. Distances are horizontal to a nail & tag LS5339 driven into the side center of trees. Posted Forest Service monument signs and Bearing Tree signs on all trees.