


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_ County of \_\_\_\_\_, California

Brief Legal Description E 1/4 COR. SEC 32, T.6S., R.20E



### CORNER TYPE

- |                   |                          |          |                          |
|-------------------|--------------------------|----------|--------------------------|
| Government Corner | <input type="checkbox"/> | Control  | <input type="checkbox"/> |
| Meander           | <input type="checkbox"/> | Property | <input type="checkbox"/> |
| Rancho            | <input type="checkbox"/> | Other    | <input type="checkbox"/> |
| Date of Survey    | _____                    |          |                          |

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner —    Left as found     Found and tagged     Established     Reestablished     Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

E 1/4 Corner Sec. 32

Found original stone (4), with 1/4 marked on west face. Chiseled an "X" on top of stone. Set a 5/8" bar 0.25' west of stone. Found old bearing trees.  
 27" W.O. (N01°E)(4)(M) 42.7'  
 (16" W.O.)(4) (41.58')(4)  
 20" W.O. Stump (N77°45'W)(4)(M) 60.5'  
 (12" W.O.)(4) (60.06')(4)

\_\_\_\_\_ monument as found and as set or reset: \_\_\_\_\_

*COPIED FROM  
RS 47/86*

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19\_\_\_\_.

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19\_\_\_\_ and examined and filed \_\_\_\_\_ 19\_\_\_\_.

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment \_\_\_\_\_