


CORNER RECORD

COUNTY OF MADERA T. 6 R. 21 MERIDIAN CALIFORNIA


CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT MAY 1990



N 1/4 SEC. 1 1/21

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH



PHYSICAL DESCR

CALIFORNIA CO
 STATATIONS USED
 ZONE

N 1/4 CORNER SECTION 1 1/21
 FOUND A 2' DIA. ROCK MOUND, FLUSH REMONUMENTED WITH F.S.M., UP 7"
 ORIGINAL BEARING TREES:
 1. A FORKED BLACK OAK, 24" DIA. WITH A BLAZED FACE 6" DEEP, BEARS N 33 3/4° W, 21.0' (N 36° W 21.12') ALL MEASUREMENTS TO E'Y FORK.
 2 OAK REMAINS BEAR S 61 3/4° E 17.9' (S 49 1/2° E 17.82')
 NEW TIES:
 3 AN INCENSE CEDAR BEARS N 79 1/4° W 20.65'
 4. A PONDEROSA PINE, BEARS N 75 1/4° E 14.84'
 5. A PK NAIL & TAG, LS 5509, IN A 5' X 3' X 4' HIGH ROCK BEARS S 5 3/4° E 51.48'
 - SET A METAL POST WITH FOREST SERVICE MONUMENT SIGNS ATTACHED 4'- NE OF THE CORNER
 - THE CORNER LIES APPROXIMATELY 600' EAST OF A CREEK, COURSE S 1/4"

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 37/61, 62

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO