


CORNER RECORD

COUNTY OF MADERA T. 6 R. 21 MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT MAY 1990



5/4 SEC. 1/21

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION CALIFORNIA STATIONS ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____	<p style="text-align: center;">S 1/4 CORNER SECTION 1/21</p> <p>FOUND NO EVIDENCE OF ORIGINAL CORNER MONUMENT OR ACCESSORIES. REESTABLISHED CORNER POSITION BY SINGLE PROPORTION. SET F.S.M. UP 11" BUILT A ROCK MOUND 3" DIA. x 1 1/2" HIGH AROUND MONUMENT.</p> <p>TIES:</p> <ol style="list-style-type: none"> 1. A BLACK OAK, 19" DIA., BEARS S 51 3/4° W 42.13' 2. AN INCENSE CEDAR, 10" DIA., BEARS N 58 1/2° W 40.23' 3. AN INCENSE CEDAR, 18" DIA., BEARS N 86 3/4° E 24.00' 4. A NAIL & TAG, LS 5509 IN E'LY SIDE OF 4 1/2' x 3' x 2' HIGH ROCK, BEARS S 0 1/4° E 20.52' <p>- SET A METAL POST WITH FOREST SERVICE MONUMENT SIGNS ATTACHED S 35° W 4'.</p> <p>THE CORNER LIES 117' W. OF A BROOK, COURSE SW'LY AND 118' N. OF THE SAME BROOK.</p>
---	--

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS ³⁷/_{61, 62}

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO