


CORNER RECORD

CITY OF MADERA T. 6 R. 21 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT MAY 1990




SW COR. SEC. 1 1/2

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

CAP INSCRIPTION DESCRIPTION



SW CORNER SECTION 1 1/2

FOUND REMAINS OF A WOODEN POST IN THE CENTER OF A 2 1/2' DIA. X 1 1/2" HIGH ROCK MOUND. REMONUMENTED WITH F.S.M., UP 9" REBUILT ROCK MOUND 2 1/2' DIA. X 1' HIGH AROUND MONUMENT.

ORIGINAL BEARING TREES:

1. A PINE STUMP, 2 1/2' DIA., BEARS S 79 3/4° E 17.1' (S 84° E 15.18')
2. A PINE STUMP, 3' DIA., BEARS S 77 3/4° W 88.4' (S 78° W 87.78')
3. A BLACK OAK, 28.6" DIA., BEARS N 78 1/2° W 76.03' (N 78 1/2° W 75.90')
4. A PINE STUMP, 2' DIA., BEARS N 2° W 27.26' (N 2° W 25.74')

NEW TIES:

5. A PONDEROSA PINE, 15" DIA., BEARS S 73° E 14.37'
6. A PONDEROSA PINE, 14" DIA., BEARS S 72 1/2° W 32.38'
7. A PONDEROSA PINE, 12" DIA., BEARS N 44° W 28.58'

- SET A METAL POST WITH FOREST SERVICE MONUMENT SIGNS ATTACHED 4' SW OF THE CORNER.

PHYSICAL

LIFOR
STATION
ZONE

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS ³⁷/_{61,62}

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO