


# CORNER RECORD


COUNTY OF MADERA T. 6 R. 21 MERIDIAN CALIFORNIA  
 CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION — DATE OF VISIT MAY 1990



W 1/4 Sec. 1 1/2

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH



W 1/4 CORNER SECTION 1 1/2

FOUND NO EVIDENCE OF ORIGINAL CORNER MONUMENT OR ACCESSORIES.  
 REESTABLISHED CORNER POSITION BY SINGLE PROPORTION.  
 SET F.S.M. UP 6". BUILT A ROCK MOUND 2" DIA. X 1/2' HIGH AROUND  
 MONUMENT.

TIES:

1. SW CORNER OF HOUSE, BEARS N 5 1/4° W 34.44'
  2. AN INCENSE CEDAR, 8" DIA., BEARS N 62° E 65.75'
  3. A WHITE FIR, 6" DIA., BEARS S 76 1/2° E 8.51' - NO BLAZE.
  4. AN INCENSE CEDAR, 13" DIA., BEARS S 28 1/2° W 27.08'
  5. A TRANSFORMER BEARS N 18 1/4° W 101.62' - DISTANCE TO A NAIL & TAG, LS 5509 IN SIDE-CENTER.
- SET A METAL POST WITH FOREST SERVICE MONUMENT SIGNS ATTACHED 4'± SW OF THE CORNER.

CALIFORNIA  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_

NORTHINGS (N) \_\_\_\_\_

EASTINGS (E) \_\_\_\_\_

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS <sup>37</sup>/<sub>61,62</sub>

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON \_\_\_\_\_ 19\_\_\_\_

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No. \_\_\_\_\_

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_  
 AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_

STATEMENT ON BACK OF SHEET

YES  NO