_		RECORD	
:	COUNTY OF MADERA T. G R. CORNER TYPE: GOVT. CORNER MEANDER R. RANCHO CORNER IDENTIFICATION — DATE OF VISIT 25 April		1FORN
	-2- w/4 cor. sec. 2		
_	CORNER — LEFT AS FOUND [X] FOUND AND TAGGED [REE	STABLISHED OBLITERATED CORNER REBUILT	
	FOUND: DEPARTMENT OF Agriculture CAPPED PIPE MONUMENT. DATED 19: BI ABOVE GROUND. Located and	capastral surv 19 IN Rock Mound Identified by	
	Forest Service Notes and Tie	5	
_	PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	<u>, in , , , , , , , , , , , , , , , , , ,</u>	
•	SEE Above		
			1.00 10
-	CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECON STATIONS USED: NGS (USC & GS) STATE COUNTY COUNTY NORTHINGS (Y)	OTHER STATION	<u> </u>
	SKETCH: (Include reference tie or witness points, remarks and topo	of area)	
		TO NEAR FACE OF	
		116 6120	
	No.		-
	OF 23" PINE ONSO WITH KTAG	NOTE: Point is 830' s.w. And At	
ROFESSIO	DATED 1936	tangent in the State Highw	Аγ.
CK NO.	55.	6 2 6	
CiVIL		TO NEAR FACE OF	
OF CALL	NOTE: BEArings Are Magnetic BEAring	s taken by USES, Using 17° Declina	tion
	SURVEYOR'S CERTIFICATE THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	THE CORNER RECORD WAS RECEIVED	
	ON OCT 2 1979	AND EXAMINED AND FILED 1879. BY: A Distribution of the contraction of	· .

DPW-15

SEAL

YES NO

STATEMENT ON BACK OF SHEET