CORNER RECORD	
COUNTY OF Madera T. 8 S R. 23	THE THE PARTY OF T
CORNER TYPE: GOVT. CORNER MEANDER RANCHO	CONTROL OTHER TO
	hwest 1/256 corner section 33 8/23
CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABL	
CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED TO IDENTIFY OR REISTABLISH PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REISTABLISH	
The corner position was re-established from ties per Record of Survey filed in	at distance-distance intersection Book 43 of Maps at pages 19-34.
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	
Set standard Forest Service aluminum monument, 2½"0.D., 30" long with a 3½"0.D. aluminum cap stamped for the corner, with LS 6806, the date (1995), and a Forest Service logo, up 2" in a small rock mound.	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND	THIRD _
	OTHER STATION STATION
TOTAL MONTHINGS (1)	Example (A)
SKETCH: (Include reference tie or witness points, remarks and topo of ar	ea)
Found Corner Ties	Cap Inscription
1. A 23" White Oak with a nail in	0.22
the side center of the root crown	S 33
(S87W), 13.7'.	NE-NE-SW
2. PK nail in centerline of paved	1/256 °
road (N23W), 34.71'.	LS 6806
	1995
(compage bearing)	
(compass bearing)	
	SED LAND SURLE
///	ST RICKI ON MILES
#	
	No. L 6827 7 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
TOLANDO	
SURVEYORS CHET CAN B. JOA	OF CALIFERENTY SURVETOR'S CIRTIPICATE
THIS CORNER RECORD WAS PRECISED BY ME OR UNDER MY	THE CORNER RECORD WAS RECEIVED SI MAN 1995
ON 29 MARCH 1 195	AND EXAMINED AND FILED TO AND THE 1995
August & Condan	TITLE: ALTING COUNTY SULVEYOL
L.S. en Color (A) No SUIC	DOCUMENT No.
No. 6806	STATEMENT ON BACK OF SHEET YES HO
OF CALIFOR	YES NO 🔯