


CORNER RECORD

COUNTY OF MADERA TOWNSHIP **6** SOUTH, RANGE **21** EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: April 19 79



NORTHWEST CORNER OF SECTION 16, 6/21.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found Rock Mound

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1½" Iron Pipe tagged "LS 4298" up 12" in rock mound.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

- N 12°W, 48.5 feet to a 40" Pine stump (original B.T.)
- N 30°E, 95+- feet to stump remaining (original B.T.)
- S 34½°E, 89.0 feet to a Black Oak (original B.T.)
- S 7½°W, 100.0 feet to a 48" stump, Pine (original B.T.)
- S 45°W, 13.7 feet to a 14" Black Oak I blazed.
- S 18½°E, 41.0 feet to a 20" triple forked Black Oak.
- N 55°W, 15.5 feet to a 24" Black Oak with K-tag & old blaze.

**Note: Copied from Parcel Map 1824
Surveyed by Stephen Jones, LS 4298.**

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES NO