CORNER RECORD

OOMITEM	
COUNTY OF MADERA TOWNSHIP 6 SOUTH, RANG	GE 21 EAST, M.D.B.&M. CALIFORNIA
	RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT: April	
WEST 1/2 CORNER OF SEC	PTION 21 6/21
WEST 4 CORNER OF SEC	110N 21, 6/21.
CORNER - LEFT AS FOUND FOUND AND TAGGED REESTA	ABLISHED OBLITERATED CORNER REBUILT
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHO	DD USED TO IDENTIFY OR REESTABLISH
Found 1" Iron Pipe tagged "LS 2737"	for witness corner per Record
of Survey recorded in Vol. 9, Page	112 of Madera County Records.
PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED	
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST	<u> </u>
STATIONS USED: NGS (USC & GS) STATE STATE	
ZONE ELEVATION NORTHI	INGS (Y) EASTINGS (X)
	· ·
•	
Note: Copied from Record of Surveyed by Joseph C. Smyt	-
adiveyed by Joseph C. Smy	LII, RCE 21650.
OUDVEYOR'S CERTIFICATE	COUNTY OUR CONTROL OF CONTROL
SURVEYOR'S CERTIFICATE THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY	COUNTY SURVEYOR'S CERTIFICATE THE CORNER RECORD WAS RECEIVED 19
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON	AND EXAMINED AND FILED 19
19	
SIGNED:	BY:
L.S. or R.C.E. No:	TITLE:

SEAL

DOCUMENT No:
STATEMENT ON BACK OF SHEET: YES

ио [