

CORNER RECORD

COUNTY OF MADERA T. 6 R. 21 M.D.B. 1M MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT 5-3 1988



NW 23 1/2


CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

⑥ NORTHWEST CORNER SEC. 23 1/2

REESTABLISHED CORNER POSITION FROM ORIGINAL B.T.'S, CORNER FALLS IN CREEK CHANNEL. SET REFERENCE MON. N. 69°02'22" W. 53.01 FROM TRUE CORNER POSITION

1. A PK NAIL & TAG L.S. 5509 IN LARGE ROCK BUTTROP IN CREEK CHANNEL, BEARS N. 30 1/4° W. 32.98
2. A NAIL & TAG L.S. 5509 IN A ROCK 6'X6'X7' HIGH OF THE EAST SIDE OF CREEK, BEARS S. 1 1/2° N. 13.92
3. A NAIL & TAG L.S. 5509 IN A ROCK 7'X6'X 5 1/2' HIGH IN CHANNEL, BEARS S. 18 1/4° W. 99.29
4. A BLACK OAK 27" DIA. HEALED BLAZE FACING SW'LY, PREVIOUSLY CUT INTO, BEARS N. 44° E. 40.89 (ORIGINAL B.T.)
5. A FIR SNAG 2' DIA. BEARS S. 24 3/4° E. 50.26 (ORIGINAL B.T.)
6. A 10" ALDER LEANING S'LY BEARS S. 4 1/2° E. 15.24 (ORIGINAL B.T.)



PHYSICAL

ALIFOR
STATION
ZONE

SKETCH: (Include reference tie or witness points, remarks and topo of area)

COPIED FROM RS 40/60-61

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO