


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 6 SOUTH, RANGE 21 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [x] MEANDER [ ] RANCHO [ ] CONTROL [ ] OTHER [ ]

CORNER IDENTIFICATION - DATE OF VISIT: December 19 74



NORTH 1/4 CORNER OF SECTION 31, 6/21.

CORNER - LEFT AS FOUND [x] FOUND AND TAGGED [ ] REESTABLISHED OBLITERATED CORNER [ ] REBUILT [ ]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2" Iron Pipe, 3" under.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [ ] SECOND [ ] THIRD [ ]

STATIONS USED: NGS (USC & GS) [ ] STATE [ ] COUNTY [ ] OTHER [ ] STATION \_\_\_\_\_ STATION \_\_\_\_\_

ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

- 12.80 feet West of Shiner in fence post.
8.70 feet East of Shiner in fence post.
42.80 feet North of Shiner in 18" Oak.

Note: Copied from Parcel Map 895
Surveyed by R. Greenwood, RCE 12406

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

\_\_\_\_\_ 19 \_\_\_\_.

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No: \_\_\_\_\_

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19 \_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_.

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No: \_\_\_\_\_ STATEMENT ON BACK OF SHEET: YES [ ] NO [ ]