


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description N.W.C. SECTION 32 T. 6 S., R. 21 E. M.D.B. & M.



### CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

### COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND & ACCEPTED A NAIL & TAG, L.S. 4261 IN TOP OF STONE  
11" x 17"; UP 12". FOUND 4 GROOVES ON WEST SIDE AND 1 GROOVE  
ON NORTH SIDE OF FOUND STONE.

A description of the physical condition of the monument as found and as set or reset: TIES

- ① A NAIL & SHINER IN A LARGE ROCK OUTCROP, BEARS S 70° 01' 01" W 41.19'.
  - ② A NAIL & SHINER IN A LARGE ROCK OUTCROP, 15' x 30' x 3' HIGH, BEARS  
N 9° 40' 24" E 31.53'.
- THE CORNER LIES 1/2" NORTH OF A FENCE CORNER  
FROM WHICH FENCES RUN SOUTHERLY AND WESTERLY

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined  
and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM AWAHNEE COUNTRY CLUB  
ESTATES SUBDIVISION, BOOK 38, PAGE 32.