CORNER RECORD

OUNTY OF MADERA TOWNSHIP & SOUTH, RAN	nge 2/ EAST, M.D.B.&M. CALIFORNIA
ORNER PE: GOV'T. CORNER MEANDER	RANCHO CONTROL OTHER
ORNER IDENTIFICATION - DATE OF VISIT: OCT 8	19_/ <i>5</i> _
•	······································
	·
3/2 SEC CAR 25	- 21 30 Di
36 SEC COR 25	136,30,31
•	
ORNER - LEFT AS FOUND FOUND AND TAGGED REES	TABLISHED OBLITERATED CORNER REBUILT
HYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND MET	HOD USED TO IDENTIFY OR REESTABLISH
IRON PIPE	
HYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUAT	ED
ALIFORNIA COORDINATE SYSTEM ORDER: FIRST	SECOND THIRD
TATIONS USED: NGS (USC & GS) STATE	COUNTY OTHER STATION STATION
	HINGS (Y) - EASTINGS (X)
ONE ELEVATION NORTH	111105 (1)
RESET THIS CORNER	FALLS 6' SW OF GULCH,
MD OF ROCKS. IRON	PIPE
	•
SURVEYOR'S CERTIFICATE	COUNTY SURVEYOR'S CERTIFICATE
HI NER RECORD WAS PREPARED BY ME OR UNDER MY	THE CORNER RECORD WAS RECEIVED 19
IRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S	AND EXAMINED AND FILED
CT ON19	
SIGNED:	BY:
	TITLE:
.s. or R.C.E. No:	DOCUMENT NO: STATEMENT ON BACK OF SHEET: YES NO
SEAL	STATEMENT ON BACK OF SHEET: YES NO

SEAL