CORNER RECORD	<u> </u>
COUNTY OF Madera T. 65 R. 22E M.D.B. & MERIDIAN	CALIFORNI
CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER	
CORNER IDENTIFICATION — DATE OF VISIT August 14 19 79	
N 1/6 cor. 9 10 6/22	
[-/-id-	•
COMES — LETT AS SOUND CO SOUND AND TACCED CO SECRETABLESIS ON SECRETARISMS	
CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT	<del>,</del>
PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH	
Established position for N /16 cor on line between	
NW cor 5 10 and w 14 cor 5 10 and halfway betw	CEN
PHYSICAL DESCRIPTION OF MONUMENTS RESULT OR PERPETUATED Set 30" alominum monumen	75
with 314" aluminum cap with Forest Service logo;	
stamped for corner with date (1919) and 45 4689.	
Monument has flared base. Built rock and aroun	-
mon Mon Up 6"	· C.
men. 1000 Ope 6	
	<del></del>
CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD	-
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION STATI	
SKETCH: (Include reference tie or witness points, remarks and topo of area)	•
Ties are from cor. Bearing trees are blazed	
and scribed 'N. B.T' for 'New Bearing Trees'	
TIES:	
1 28 3/4° E 43.55' to 5 & K in 12.5" dio Incense C	edar
29 34° E 32.33' to S&N in 26.2" dia Sugar Pin	
27 17 2 02 00 12 00 14 20 2 210 0 2 900 1700	
ND S	
ARNOLD CO	
HEN \2013	
/ <b>*</b> //	
4689	
CALIFORNIA	
SURVEYOR'S CERTIFICATE COUNTY SURVEYOR'S CERTIFICATE	<del></del>
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY THE CORNER RECORD WAS RECEIVED	_19
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT AND EXAMINED AND FILED	
	-

DOCUMENT No.

STATEMENT ON BACK OF SHEET