


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description E 1/4 COR SEC 17 6/22



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

(2A) EAST 1/4 CORNER SEC. 17 6/22
 FD. 36" W. FIR, CUT INTO HEAL TO EXPOSE ORIG.
 BLAZE AND AXE MARKS. RESET CORNER W/
 U.S.F.S. MON. IN ROCK MD. L.S. 4298. CORNER
 FALLS IN OLD SKID TRAIL.
 FROM WHICH BEARS:

29" S. PINE	N. 31° E.	28.80	
37" S. PINE	S. 30° W.	30.36	
36" W. FIR	S. 53° E.	12.03	(ORIG.)
N. 45° W.	2.0 TO U.S.F.S. POST		

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on _____

Signed _____ P.L.S or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S or R.C.E. No. _____

Title _____

County Surveyor's Comment COPIED FROM BK 34 PG 5-9