


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description NE COR SEC 17 6/22

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

① N.E. CORNER SEC. 17 6/22
 FOR 47" FIR, CUT 18" INTO SCAR TO EXPOSE
 BLAZE AS ORIG., CORNER FALLS WITHIN
 33" CEDAR
 FROM WHICH BEARS:

A desc	16" FIR	N. 52° E.	22.00
	22" FIR	N. 51° W.	25.20
	47" FIR	S. 78° E.	38.50
	N. 45° E.	4.0 TO U.S.F.S. POST	
	SOUTH ON LINE 10.00 TO U.S.F.S. W.C. MON. L.S. 4298		
	WEST ON LINE 10.00 TO U.S.F.S. W.C. MON. L.S. 4298		
	S. 68° 23' 26" E. 16.27 TO 1/2" IRON PIPE NO TAG		

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on _____

Signed _____ P.L.S or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S or R.C.E. No. _____

Title _____

County Surveyor's Comment COPIED FROM BK 34 PG 5-9