


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description N 1/4 COR SEC 27 6/22**CORNER TYPE**

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

④ NORTH 1/4 CORNER SEC. 27 6/22
 PD 1" I.P. L.S. 4126 AND 30° CEDAR STUMP W/ U.S.F.S. BT. SIGN
 "1941" B.R.C. - OLD BLAZE FACE CAN BE SEEN AT 12" DIA.
 RESET W/ U.S.F.S. MON. IN ROLL NO. L.S. 4298
 FROM WHICH BEARS:

9 1/2" FIR	S. 50° E.	19.64
30° CEDAR STUMP	S. 13° W.	34.8 (ORIG.)
14" B. OAK	S. 29° W.	35.55
9" CEDAR	N. 29° W.	11.20
S. 45° E.	2.0 TO U.S.F.S. POST	

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on _____

Signed _____ P.L.S or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S or R.C.E. No. _____

Title _____

County Surveyor's Comment COPIED FROM BK 34 PG 5-9