


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description W 1/4 COR SEC 27 6/22



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

- N. _____
- E. _____
- Zone _____ NAD27 NAD83
- NAD83 Epoch _____
- Elev. _____
- Vert. Datum: NGVD29 NAVD88
- Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

(17) WEST 1/4 CORNER SEC. 27 6/22
 PD ORIG. ROCK MD. N 1/6" FIR N/B (70° BANG CORNER)
 ALSO PD. LARGE S. PINE STUMP AND UPRIGHTED OLD FIR B.T.'S
 AND 2 LIVE TREES RESET N/V U.S.F.S. MON. IN ROCK MD L.S. 4298
 FROM WHICH BEARS:

A description

- S. PINE STUMP N. 27° E. 48.45 (ORIG.)
- 16" FIR N. 70° E. 28.43
- SOUTH 12.5" DEAD AND DOWN FIR (ORIG.)
- 14" FIR S. 52° E. 10.40
- 30" S. PINE S. 29° W. 18.64
- N. 15" N. 4.0 TO U.S.F.S. POST

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on _____

Signed _____ P.L.S or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S or R.C.E. No. _____

Title _____

County Surveyor's Comment COPIED FROM BK 34 PG 5-9