


CORNER RECORD

Document Number _____

City of _____

County of _____, California

Brief Legal Description E 1/4 COR SEC 30 4/22**CORNER TYPE**

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

39 EAST 1/4 CORNER SEC. 30 4/22
 FD. 14" B. OAK W/ BLAZES ON 4 SIDES W/ 1" I.P. L.S. 2137
 IN ROCK MD. ON N/S
 FROM WHICH BEARS:

A description	10" CEDAR	EAST	8.00 (W.O. GENTRY BLAZE)
	19" CEDAR	S. 20° W.	25.43
	13" PINE	N. 38° W.	12.90 (W.O. GENTRY BLAZE)
	N. 45° E.	6.20 TO U.S.F.S. W.C. MON. IN ROCK MD.	
	N. 45° E.	8.00 TO U.S.F.S. POST	
	N. 36° 45' 03" W.	6.50 TO U.S.F.S. W.C. MON. IN ROCK MD.	
	N. 37° W.	8.00 TO U.S.F.S. POST	

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on _____

Signed _____ P.L.S or R.C.E. No. _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____

and examined and filed _____

Signed _____ P.L.S or R.C.E. No. _____

Title _____

County Surveyor's Comment COPIED FROM BK 34 PG 5-9