


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 6 SOUTH, RANGE 22 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT: March 19 77



NORTHWEST CORNER OF SECTION 35, 6/22.

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found corner tree - 38" Sugar Pine & 3 bearing trees.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1 1/2" Iron Pipe with Brass Cap "LS 4126" for witness corner, N 88°24'17"W , 28.53 feet from corner.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []

STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION STATION

ZONE ELEVATION NORTHINGS (Y) EASTINGS (X)

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

Black Oak stump (B.T.) N 85°E , 26.4 feet
14" Black Oak (B.T.) S 70°W , 13.0 feet
36" White Fir (B.T.) S 42°E , 42.0 feet

Note: Copied from Record of Survey for Art Kalsbeek Surveyed by C. Sikora, LS 4126.

VOL 23 PAGE 64

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON

19

SIGNED:

L.S. or R.C.E. No:

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED 19

AND EXAMINED AND FILED 19

BY:

TITLE:

DOCUMENT No: STATEMENT ON BACK OF SHEET: YES [] NO []