


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 6 SOUTH, RANGE 24 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



NORTHWEST CORNER SECTION 5 6/24

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 12" B. OAK WITH SCARS ON 4 SIDES, REGROWTH OF ORIG. CORNER TREE ALSO FD. ORIG. SCRIBING ON PIECE OF ROTTEN OAK ADJ. TO REGROTH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET STAD. U.S.F.S. MON. 2" ALUMINUM PIPE 25" LONG WITH 3/4" ALUMINUM CAP STAMPED L.S. 4727 S 9° 26' 49" W 5.00' FOR W.C.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

N 55° W	29.88'	TO	30" PINE NEW BT
S 55° W	31.80'	TO	24" PINE NEW BT
N 50° E	9.46'	TO	10" OAK NEW BT
N 66° W	33.00'	TO	34" PINE WITH K TAG
S 18° W	50.16'	TO	34" PINE MARKED "X"

COPIED FROM R/S FOR WAGNER BY TIM SNYDER L.S. 4727

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES NO