


# CORNER RECORD

COUNTY OF MADERA T. 6 S. R. 24 E. MD MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER  MEANDER  RANCHO  CONTROL  OTHER   
 CORNER IDENTIFICATION -- DATE OF VISIT FEB. 7 1991



CENTER-WEST 1/16 CORNER SECTION 5

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  RESULT


PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

THERE IS NO RECORD OF THIS CORNER BEING SURVEYED.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED I SET A 3/4x30 INCH IRON PIPE, UP 4 INCHES, AT THE LOCATION AS DETERMINED BY SINGLE PROPORTION MEASUREMENT. FOR BEARING TREES, I MARKED A 4-INCH DBH PONDEROSA PINE, 78° AT 1.6 FEET AND A 5-INCH SUGAR PINE, 285° AT 10.7 FEET.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
 STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
 ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)



**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEB. 7 1991

SIGNED:

L.S. or R.C.E. No. LS 4126

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19\_\_\_\_  
 AND EXAMINED AND FILED \_\_\_\_\_ 19\_\_\_\_

BY: \_\_\_\_\_  
 TITLE: \_\_\_\_\_

DOCUMENT No. \_\_\_\_\_