


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 6 SOUTH, RANGE 24 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19____



WEST 1/4 CORNER SECTION 5 6/24

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND SMALL MOUND OF ROCKS AS PER FOREST SERVICE CORNER RECORD
DATED 1970

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET STANDARD U.S.F.S. MON. 2" ALUMINUM PIPE 25" LONG WITH 3/4"
ALUMINUM CAP STAMPED L.S. 4727

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

N 37° W	20.30'	TO	BLK. OAK CLUSTER POSS. REGROWTH
S 3° W	50.10'	TO	30" DEAD & DOWN PINE POSS. ORIGINAL BEARING TREE
S 55° W	36.60'	TO	24" YELLOW PINE NEW BT
N 20° E	42.30'	TO	15" YELLOW PINE NEW BT

COPIED FROM R/S FOR WAGNER BY TIM SNYDER L.S. 4727

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____.

BY: _____

TITLE: _____

DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES NO