


File No. E-3 **CORNER RECORD (SEARCH)** Ticket or Survey No. _____ Cor. No. _____
 (Rev. FSM 2131.4)
 T. 65 R. 24B R.D. Minares County Madera
 Merid. MT Doble N.F. Sierra State California



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

6 ft. Sugar Pine snag S4°W 105 IKs
 stump hole (PP) N35°E 26 IKs

PHOTO IDENTIFICATION DATA 1970
 Photo No. EWA M-163 Color
 Filed At. North Fork
 Object Ident. _____
 Ident. By David A. Smith
 Signature

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

K tag placed on 6" I.C. on W edge of road 2 1/2 mi East to corner. K tag is about 60 feet ± north of fence line. Fence line is in Forest Service.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency

Signature David A. Smith Title Forester Division TM Headquarters North Fork Date June 5, 1975 7100-52 (3.68)

S 1/4 SECTION 6

0624

A rock mound was placed around a 2 ft high cedar post with a K tag and boundary call for the corner (this mound is not original).

ACCESSORIES DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

K tag placed on 47" IC S10°W 27 FT to corner

K tag placed on 15" PP N25°W 45 1/2 FT to corner

BT & Attention sign placed on SP BT. Red bend painted around BT & RPS.

Work Done By _____ Title _____ Date _____ State Registration No. or Agency _____

Certified Cor Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

SP BT is one of two SP snags. This SP meets bearing and distance with the stump hole to the second BT. The corner is on line between known corners and fits the calls to the creek well. This line is not due E-W, it is approximately 84 1/2° SE from the corner of $\frac{116}{1217}$ to $\frac{615}{718}$. Found old rusted K tag by edge of stump hole. This corner appears to be good but all evidence will be gone in a few years.

Index File No. T. R. M. Tract or Surv. No. Cor.