


CORNER RECORD

COUNTY OF MADERA TOWNSHIP 6 SOUTH, RANGE 24 EAST, M.D.B.&M. CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT: _____ 19 _____



NORTH 1/4 CORNER SECTION 7 6/24

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND AS PER FOREST SERVICE CORNER RECORD DATED 1975

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET STANDARD U.S.F.S. MON. BEING A 2" ALUMINUM PIPE 25" LONG WITH A 3/4" ALUMINUM CAP STAMPED L.S. 4727

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (INCLUDE REFERENCE TIE OR WITNESS POINTS, REMARKS AND TOPO OF AREA)

TIES:

S 20° W	# 47.72'	TO	10" CEDAR NEW BT
N 75° E	36.65'	TO	14" OAK NEW BT
NORTH	1.00'	TO	FENCE CORNER FEN. RUNS N & W
N 35° E	17.00'	TO	STUMP HOLE OF ORIG. BT
S 3° W	69.70'	TO	5' PINE STUMP ORIG. BT

COPIED FROM R/S FOR WAGNER BY TIM SNYDER L.S. 4727

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYOR'S ACT ON _____ 19 _____.

SIGNED: _____

L.S. or R.C.E. No: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____

AND EXAMINED AND FILED _____ 19 _____.

BY: _____

TITLE: _____

DOCUMENT No: _____
STATEMENT ON BACK OF SHEET: YES NO