


CORNER RECORD

COUNTY OF MADERA T. 6 S. R. 24 E. MD MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT FEB. 7 1991



WEST 1/16 CORNER SECTION 8

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


THERE IS NO RECORD OF THIS CORNER BEING SURVEYED.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

I SET A 3/4x30 INCH IRON PIPE, UP 4 INCHES, AT THE LOCATION AS DETERMINED BY SINGLE PROPORTION MEASUREMENT. FOR BEARING TREES, I MARKED A 5-INCH DBH PONDEROSA PINE, 270° AT 23.8 FEET AND A 38-INCH PONDEROSA PINE, 59 1/2° AT 28.6 FEET.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEB. 7 1991

SIGNED: _____

L.S. or R.C.E. No. LS 4126

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____