

CORNER RECORD

COUNTY OF MADERA T. 6 S. R. 24 E. MD MD MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT FEB. 1 1991



NORTHWEST CORNER SECTION 8

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT


PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

I FOUND TWO REFERENCE MONUMENTS SET BY THE FOREST SERVICE. THESE ARE BOTH STANDARD US GOVERNMENT (USFS) ALUMINUM MONUMENTS. THE CORNER BEARS $N84^{\circ}56'52''E$, 25.00 FEET FROM ONE MONUMENT AND $S20^{\circ}02'39''E$, 25.00 FEET FROM THE OTHER. THE MONUMENT SET BY SNYDER WAS REPLACED TO PREVENT THE LOCATION BEING LOST TO EROSION.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEB. 1 1991

SIGNED:

L.S. or P.C.E. No. LS 4126

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____ TITLE: _____

DOCUMENT No. _____