


CORNER RECORD

COUNTY OF Madera T. 6 S. R. 24 E. M.D.B. & M. MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER ALIENOR RANCHO CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT October 28 19 85



The west 1/4 corner of section 9 6/24.
 (common to sections 8 and 9)

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found and Accepted: A 1" O.D. iron pipe, tagged RCE 12406, up 7", no rock mound.
 (Reference Tract No. 167 filed in Book 15 of Maps at pages 175 - 179 of Madera County Official Records.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Left monument as found, built a 2' dia. x 7" high rock mound around monument.
 Set a metal post with Forest Service monument signs attached, 4' ± NE of the corner.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USL & GS) STATE COUNTY OTHER STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

Corner Ties:

Original Bearing Trees:

1. A large Sugar Pine in the NW quadrant, as noted on plat of Tract No. 167 filed in Book 15 of Maps at pages 175 - 179 of Madera County Official Records.

New Bearing Objects:

2. A Ponderosa Pine, 7" dia., bears N 47° E, 89.23'.
3. A White Fir, 11" dia., bears S 09° E, 39.46'.
4. A White Fir, 18" dia., bears N 25° W, 83.66'.

Bearings are ± 2°

G-9
 F.B. 35/77
 Job No. 85-8
 (Continued on back)


SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Dec 1985
 SIGNED: Howard Arnold Cohen
 L.S. No. 4689

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19____
 AND EXAMINED AND FILED _____ 19____
 BY: _____
 TITLE: _____
 DOCUM. No. _____
 STATEMENT ON BACK OF SHEET YES NO

Bearings are to the center of trees at the base. Distances are horizontal to a nail and tag (stamped LS 4689) driven into the side center of the root crown.

Posted Forest Service monument and bearing tree signs.

The monument lies 8" ENE of a fence corner, fences run southerly and westerly.



0624300540