


CORNER RECORD

COUNTY OF MADERA T. 6 R. 24 MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT 8-1 1988



W 1/4 SEC. 21 1/24

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND ROCK MD. ON LARGE ROCK DOME AND 2-ORIG. BTs,

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

RESET WITH 1" IRON PIPE DRILLED INTO ROCK WITH USFS CAP

ALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 1) PINE 9" N. 0° 05' 23" E 109.26 ORIG. BT WITH BLAZE
(THIS TREE IS GROWING OUT OF SOLID ROCK AND IS VERY OLD BUT STUNTED IN SIZE)
 - 2. DRILL HOLE WITH USFS POST IN SAME N. 8° 21' 40" E 45.29
 - 3. USFS POST, S. 45° W 4" IN DRILL HOLE
 - 4. P. PINE 6" S 24 3/4° E 58.06 N.B.T.
 - 5. Y. PINE 28" DEAD & DOWN WITH "K" TAG. N° 47° W 73.9 ± ORIG. BT.
- COPIED FROM RS 36/07 BY JONES & SNYDER

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No.: _____

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET

YES NO