


CORNER RECORD

COUNTY OF MADERA T. 7 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT DEC. 1989



N 1/4 SECTION 22 7/19

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
METHODS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____

SKETCH: (Include reference to)

1/4 CORNER
PRELIMINARY POSITION DETERMINED BY
PROPORTIONATE MEASUREMENT USING SE COR. SEC. 15,
W 1/4 COR. SEC. 15, SW COR. SEC. 16 & W 1/4 COR. SEC. 27
FELL 587' W, 9.7' FROM FENCE CORNER, ACCEPTED
FENCE CORNER POST AS PERPETUATION OF ORIGINAL
MONUMENT. SET 5/8" ϕ BAR WITH CAP L35339
S86°28'07"W 1.00' FROM FENCE CORNER POST.
SET NAIL & TAG L35339 IN SIDE OF NEW BEARING TREE:
16" ϕ WHITE OAK N87°E, 66.10'

GRUPE DEED: VOL. 206, PAGE 392, MARIPOSA COUNTY RECORDS
DEED: BOOK 1830, PG. 630, M.C.R.

COPIED FROM RS 36/54

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET