


CORNER RECORD

COUNTY OF MADERA T. 7 R. 19 MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT DEC. 19 89



NW cor. Section 22 7/9

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

(Fold)

SKETCH: (Include reference tie or witness points, rem)

SECTION CORNER
THOROUGH SEARCH OF AREA, NOTHING FOUND.
SET 5/8" ϕ BAR WITH CAP LS5339 AT POSITION
ESTABLISHED BY DOUBLE PROPORTIONATE
METHODS 28' \pm EAST OF TREE TO TREE N-S
FENCE, MONUMENT IS 240' \pm NORTHERLY OF
RAVINE TO EAST (283.8') (1).
SET NAIL & TAG 5339 IN SIDE CENTER OF
ROOT CROWN OF NEW BEARING TREES:
16" ϕ WHITE OAK S14°W 50.58'
7" ϕ WHITE OAK S17°E 53.00'
19" ϕ WHITE OAK N23°W 72.71'

Copied from RS 36/54

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
SECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON _____ 19____

SIGNED: _____

L.S. or R.C.E. No. _____

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. _____

STATEMENT ON BACK OF SHEET