


# CORNER RECORD

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MADERA, California

Brief Legal Description \_\_\_\_\_



### CORNER TYPE

- Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey SEPT. 17, 1995

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

A description of the physical condition of the monument as found and as set or reset:

\_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

NORTH 1/4 CORNER, SECTION 23 7/19  
 PD (2) ORIG. B.T.'s, SET 98" REBAR L.S. 5509  
 IN POUNDED ROCK MTD. FROM WHICH BEARS:  
 N+T IN 3" DIA. ROCK N. 43°W 99.42  
 N+T IN 9" DIA. ROCK N. 66°W 123.58  
 N+T IN 3" DIA. ROCK S 60°E 117.12  
 36" W. OAK S 52°E 18.76  
 26" W. OAK N 24°W 51.72

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ L.S. or R.C.E. Number \_\_\_\_\_

### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received \_\_\_\_\_ 19 \_\_\_\_ and examined and filed \_\_\_\_\_ 19 \_\_\_\_ .

Signed \_\_\_\_\_ Title \_\_\_\_\_

County Surveyor's Comment COPIED FROM JONES & SNYDER  
RECORD OF SURVEY, RECORDED IN BOOK 44 OF MAPS  
AT PAGE 145