


CORNER RECORD

Document Number _____

City of _____

County of MADERA, California

Brief Legal Description _____



CORNER TYPE

- Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey SEPT. 17, 1995

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

A description of the physical condition of the monument as found and as set or reset:

*WEST 1/4 CORNER SECTION 23 7/19
 PD 1 1/4" I.P., R.E. 842 IN ROCK HD.
 FROM WHICH BEARS
 1 1/4" I.P. NO TAG, UP 18" N 88°30'37"E. 124.34
 1 1/2" I.P. IN ROCK HD S 0°36'05"E. 69.94
 30" SNAKE (ROTTER) N 52° E.
 WELY 20' TO & PAVED ROAD*

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on _____ 19 ____ .

Signed _____ L.S. or R.C.E. Number _____

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received _____ 19 ____ and examined and filed _____ 19 ____ .

Signed _____ Title _____

County Surveyor's Comment COPIED FROM JONES & SNYDER RECORD OF SURVEY, RECORDED IN BOOK 44 OF MAPS AT PAGE 145